



Changes in the AMF CAD data

Toggle clamps				
Item no.	Order no.	Reason	Internet update	OFFline CD from Version
6847GK	94672	New	29.04.05	5.03
6847GKNI	95596	New	29.04.05	5.03
6829SP	93674, 93682, 93690, 93708, 93716	New	29.04.05	5.03
6829AD	92429, 92437, 92452	New	29.04.05	5.03
6820F-4	92049	Correction	29.04.05	5.03
6820N-4	91991	Correction	29.04.05	5.03
6830 -0	93005	Correction	27.07.05	6.07
6830NI-0	95141	Correction	27.07.05	6.07
6832 -0	93203	Correction	27.07.05	6.07
6811P	90894	Correction	21.11.05	6.07
6812P	90929	Correction	21.11.05	6.07
6842-5	94250	Correction	21.11.05	6.07
6800 / 6802 / 6803 / 6804 / 6805 / 6806 / 6809P / 6810P 6830 / 6832 / 6833 / 6834 / 6840 / 6841...	All	<u>Complete update</u>	13.02.06	6.07
6833-1	93179	New	22.02.06	6.07
6820F	92015, 92023, 92031, 92049	Correction	09.10.06	



Mechanical clamping elements				
Item no.	Order no.	Reason Reason	Internet update	OFFline CD from Version
6325	74682, 74690	New	29.04.05	5.03
6486-24	71787	New	29.04.05	5.03
6498	73890	New	29.04.05	5.03
6498FT	73908	New	29.04.05	5.03
7500	74096, 74104, 74112	New	29.04.05	5.03
7500F	74153, 74161	New	29.04.05	5.03
7500Z	74120, 74484, 74476, 74492	New	29.04.05	5.03
7500T	74138, 74146	New	29.04.05	5.03
7500D	74419, 74427, 74435, 74443	New	29.04.05	5.03
6400	72447	Correction	30.05.05	6.07
DIN 6319G	82024	Correction	30.05.05	6.07
6314AV	74591, 74625, 74633, 74641, 74658, 74666	New	30.05.05	6.07
6314V	72801, 72827, 72942, 70300, 73064, 73072	Correction	30.05.05	6.07
6314S		Correction	30.05.05	
6315V	73189, 73197, 73205, 73247, 73254, 73262, 73288	New	30.05.05	6.07
6316V	71274, 71282, 71290, 71308, 71316, 71332, 71324	Correction	30.05.05	6.07
Complete update		Structural errors rectified	30.05.05	6.07
6430	72553, 72561, 72579, 72587	Spindle head	11.08.05	6.07
6435	72637, 72645, 72652, 72660	Spindle head	11.08.05	6.07
6438	75705, 75713, 75721	Spindle head	11.08.05	6.07
6430	78352, 78378, 78402, 78444	NEW: round spindle head	21.11.05	6.07
6435	78477, 78592, 78600, 78618	NEW: round spindle head	21.11.05	6.07
6438	78634, 78642, 79087	NEW: round spindle head	21.11.05	6.07
7500E-25 7500S-25	75937, 75945, ... 74096, 74104, ...	New Structural errors rectified	13.02.06	6.07
7500G, 7500A	74872, 79715, 79723	NEW !	09.10.06	
6498FR	73916	NEW !	09.10.06	
6498, 6498FT	73890, 73908	Update	09.10.06	
6314V, 6316V, 6314AV, 6315V, DIN6318, 6318B, 6321, 6326, 6475, 6500E, 6501	All	Update	09.10.06	
6400M	73320, 73361, 73403	NEW !	09.10.06	



ANDREAS MAIER GmbH & Co. KG

Waiblinger Straße 116

D-70734 Fellbach

www.amf.de

cd-hotline@amf.de

Updated 31.10.06 / Page 3 of 6

N:\Übersetzungsdaten\Eingang_CADRevision_30.10.06\AMF-CAD Revision_en.doc

6430S, 6435S, 6438S	All	Hexagonal spindle head	09.10.06	
6600, 6610, 6612, 6614, 6616	All	Update	09.10.06	
DIN787	87643, 87783, 87809 All	NEW ! Strength class added.	09.10.06	
DIN6323	All	Update	09.10.06	
6347PSP/ PP/ PS 6348PSP/ PP/ PS 6349PP	All	NEW !	09.10.06	



Hydraulic clamping systems				
Item no.	Order no.	Reason Reason	Internet update	OFFline CD from Version
6951N	69500, 61879	Correction	27.07.05	6.07
6951	69112, 69138, 69153	Correction	27.07.05	6.07
6951FZN	69351, 66944	R and AF added Change: ØA	27.07.05	6.07
6951GZN	69377, 65870	T added, change: size 22: N, P / size 33: D	27.07.05	6.07
6951KZN	69336, 65995	R, AF added	27.07.05	6.07
6951FN_DW	69484, 69492, 66290, 66332	R, AF added Change: All = stroke M, Size 33: ØA, N	27.07.05	6.07
6951FN_EW	69443, 69468, 62224, 65987	R added Change: All = stroke M, Size 33: ØA, N	27.07.05	6.07
6951GN_DW	69765, 69781, 69120, 65805	Change: Stroke K Size 22: N, P / size 33: D, L	27.07.05	6.07
6951GN_EW	69757, 69773, 69476, 69963	Change: Stroke K Size 22: N, P / size 33: D, L	27.07.05	6.07
6951KN_DW	69401, 69427, 61903, 61929, 65912, 65920, 61861, 61887	R, AF added Change All = stroke M, Size 33: ØA, N	27.07.05	6.07
6951KN_EW	69369, 69385, 65888, 65896	R, added Change: All = stroke M, size 33: ØA, N	27.07.05	6.07
6951G	68619, 68635, 68650, 68676, 68692, 68718, 68734, 68759, 68452, 68478, 68429, 68445 68460, 68486, 68502, 68627	Change: D, E, F, G	27.07.05	6.07
6951F	68221, 68247, 68262, 68288, 68387, 68403, 68411, 68437	Change: ØA	27.07.05	6.07
6951K	68726, 68742, 68767, 68775, 68791, 68833, 68858, 68874, 68890, 68916, 68932, 68957	Change: ØA D, E, F, G	27.07.05	6.07
6951KZ	66489, 66514, 66530, 66555, 66571, 66597	Change: ØA	27.07.05	6.07
6951FZ	66480, 66506, 66563, 66589	Change: ØA	27.07.05	6.07
6928G	68189, 68205	Change: C, D, E, F, <size-14>ØA	27.07.05	6.07
6927G	68148, 68163	Change: C, D, E, F, <size-14>ØA	27.07.05	6.07
6959K	320564, 320580, 320598 320606	NEW	27.07.05	6.07
6959-01-10	320622	NEW	27.07.05	6.07



6959-05-10	320630	NEW	27.07.05	6.07
6951WN	320475, 320465, 320473	NEW	27.07.05	6.07
6951N WN	320481, 320499	NEW	27.07.05	6.07
6965	320333, 320341, 320358	NEW	03.08.05	6.07
6930D	320507, 320515, 320523 320531, 320549, 320556	NEW	11.08.05	6.07
6958	320663	NEW	11.08.05	6.07
6959K – 16 / -25 6959K – 32 / -40	320564, 320580 320598, 320606	Change: Threaded hole for O-ring added	31.10.05	6.07
6959K-160 / -250 6959K-320 / -400	322016, 322024 322032, 322040	NEW	31.10.05	6.07
6960C	66647, 66640, 66662	Correction	31.10.05	6.07
6972D-12 6972D-20 6972D-32	320150 320168 320614	NEW Correction NEW	31.10.05	6.07
6972G – 12	320887	NEW	31.10.05	6.07
6972W - 12	320903	NEW	31.10.05	6.07
6972GR-12	321620	NEW	31.10.05	6.07
6972 -05 / -20 6972 -32 / -50	66993, 67439, 67124, 67447	Correction	31.10.05	6.07
6972F-05 / -20 6972F-32 / -50	66951, 66969, 66977, 66985	Correction	31.10.05	6.07
6977 -05 / -20 6977 -32 / -50	67371, 67512, 67421, 67520	Correction	31.10.05	6.07
6951K -**-11 6951K -**-22	68726, 68767, 68791, 68858, 68890, 68932 68742, 68775, 68833, 68874, 68916, 68957	Correction	31.10.05	6.07
6951KZ -**-10 6951KZ -**-20	66498, 66530, 66571 66514, 66555, 66597	Correction	31.10.05	6.07
<u>Complete update</u>		Structural errors rectified	14.12.05	6.07
6958- 08- 05 6958- 08- 06	320309 in 322248 320663 in 322255	Order no. corrected	13.02.06	6.07



Clamping and fixture systems				
Item no.	Order no.	Reason Reason	Internet update	OFFline CD from Version
6370A-xxx-xxx	302828, 302836, 302844 302851, 302869, 302877 302885, 302893	New	29.04.05	5.03
6370B-xx-xxx	302901, 302919, 302927 302935, 302943, 302950 302968, 302976	New	29.04.05	5.03
6370E-xxx-xxx	302984, 302992, 303008 303016, 303024, 303032 303040, 303057	New	29.04.05	5.03
6370S2-xxx-002	303289, 303297	New	29.04.05	5.03
Set TYPE 20 and TYPE 40		Set added	30.05.05	6.07
6370A-xxx-xxx	303487, 303529	New	11.08.05	6.07
6370E-xxx-xxx	303602, 303628	New	11.08.05	6.07
6370N-xx-xxx	303610, 303636 304519, 304535	New	11.08.05	6.07

V5.03 Data as of 24.03.2005
 V6.07 Data current as of 15.07.06

Technical support

Please send your questions with a description of the problem to cd-hotline@amf.de or fax number +49 (0) 711 575725. We will solve the problem for you right away.

Your AMF Service Team
cd-hotline@amf.de